

# Calibration Tool v2.0

The exact procedure always depends on the operator, and the equipment and tools used.

Therefore, only a description of the basic procedure is possible:

## Calibration in x-y

The bare module support (fixed) and the frame (loose) have markings.

Move the frame so that the markings are aligned in the x and y directions.

An accuracy of 5  $\mu\text{m}$  is sufficient.

## Calibration in z

The bare module support (loose) must be parallel to the support points of the flex jig on the frame.

An accuracy of 7  $\mu\text{m}$  is completely sufficient here.

Finally, the frame must be screwed together.

The coarse adjustment screw of the glue gap height should be set 6.50  $\mu\text{m}$  below the contact points of the flex jig.

## Wrap-up

It is advisable to record all relevant data again at the end of the calibration (actual state) and document it in a calibration report.